Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Black No. 1 AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

Part I	Site Identification, Location and Status		
Site Names and ID numbers as applicable			
Mine ID:	512		
Map ID:	N255		
CERCLIS:	NNN000908909		
Navajo Abandoned Mine Land Reclamation Program: NA-0329			
Local name / Aliases: Flag No. 2; Black # 1; Flag #2			
Chapter and local area: Round Rock Chapter			
County: Apa	ache State: Arizona		
Lat/Long: 36.5000600397 N / -109.252632086 W			
Nearby road and highway: Indian Route 33 Local Post Office: Cove, AZ			
Surface Land Status: check one or more and provide ownership and contact information below			
Tribal Trust I Private Bureau of Lat State	Tribal Fee Land		
Subsurface Mineral Rights:			
No information on subsurface mineral rights ownership was found in the EPA/AUM Database.			
Claim and op	erator information:		
the operator of	surface land status is classified as Tribal Trust Land. Historical documents showed the mine as Kerr McGee in 1955. No other historical ownership / lease as identified in the EPA/AUM database.		
Number of re	sidential structures within 200 feet of mine:		
None			
Estimated volume of mine waste onsite:			
1,389 yd ³			

Part II Summary of radiological readings

Highest gamma radiation measurement:

449,928 counts per minute (cpm)

Describe any other radiological measurements:

A total of 2,510 gamma radiation measurements were collected from the mine site, ranging from 14,762 cpm to 449,928 cpm. Measurements in the vicinity of the waste debris were found at levels in up to 122,000 cpm. Measurements near the adits were found at levels up to 449,928 cpm. The measurements are represented in Figures 1 and 2.


Background Locations

Average background = 13,969 cpm

#1 13,607 cpm #2 14,331 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 2510

 Minimum:
 14762,00000

 Maximum:
 449928,00000

 Sum:
 180402280,00000

 Mean:
 71873,41833

 Median:
 41562,00000

 Standard Deviation:
 67687,29419

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: Yes

NAMLRP Project Number: NA-0329

NAMLRP Mine features: 2 Portals: ID# 846, 847; Site ID# Cov212, Cov213

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:

Adits

Two stone-sealed adits were observed in the eastern portion of the site; one possible adit, marked with white paint along an inaccessible cliff face

Waste Piles

Inaccessible waste rock and wood debris down the eastern slope, approximately 75' x 100' x 5', with a total estimated volume of 1,389 yd³

Pits

None

Shafts

None

Other Debris and Mine Features

Wood mining-debris was observed atop the main waste debris pile

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Black No. 1 mine consists of an area of 19,124.22 m². The mine was identified as being operational in 1955. Historical documents showed the operator of the mine as Kerr McGee in 1955. While operational, the mine had a total reported production volume of 1,407 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): Black No.1 **Chapter:** Round Rock

Decision Criteria

Is there an unreclaimed waste pile at the site? Yes

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? Yes

Is the cap/seal functionally intact? Yes

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

2 sealed adits; 1 inaccessible possible adit; unreclaimed waste pile found heading down inaccessible cliff face

Part VI Photos



Photo 1. Mine debris along cliff face, and two sealed adits



Photo 2. Possible adit/portal, inaccessible



Photo 3. Cliff faces throughout site



Photo 4. Debris down steep grades, and inaccessible possible adit



Photo 5. Sealed adit



Photo 6. Additional sealed adit

9



Photo 7. Wood mine debris



Photo 8. View South from Black No 1 mine site


Name:

Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861


Eugene Esplain (928) 871-7331			
Title or official role (if any) Navajo EPA Superfund Program			
Address PO Box 2946, Window Rock, AZ 86515			
Information provided <u>Lead Regulatory Agency</u>			
Name			
Title or official role (if any)			
Address			
Telephone number			
Information provided			
NI.			
Name			
Title or official role (if any)			
Telephone number			
Information provided			
Name			
Title or official role (if any)	_		
Telephone number			
Information provided			

Figure 1 - Gamma Radiation Measurements, Above Two Times Background Black No. 1 Mine (512) Round Rock Chapter, Navajo Nation, Arizona



< 2X Backgound > 2X Background Gamma survey conducted 10/2009 Measured as counts per minute (cpm)


Average background = 13,969 cpm



General Direction Down-Slope Mine Claim Boundaries



Figure 2 - Gamma Radiation Measurements **Black No. 1 Mine (512)** Round Rock Chapter, Navajo Nation, Arizona



Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



Observed Waste Pile



Observed Adit



Inaccessible due to steep grades



General Direction Down-Slope



Mine Claim Boundaries

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 13,969 cpm

